


STATE North Carolina	COUNTY Gates 1p 1d		TOWN OR VICINITY Gatesville vicinity
INDEX NUMBER NC 37-GATV.V 2-	MONUMENT ✓ John Roberts House, Carter Farm		
REPRESENTED IN NEGATIVE FILE	H.A.B.S. SURVEY NO. NC-34	Owner: J. N. Carter Date of erection: early 18th C.	
PUBLISHED PHOTOGRAPHS	Present condition: poor		
PUBLISHED DRAWINGS	✓ Description: Frame; story and a half; gable roof; end chimney, rebuilt in common bond.		
6-20 6-8369		No windows in end elevation except one in gable. Long elevations identical, one door and one window; sash missing, probably 9/9; doors in very bad condition but richly pan- eled with eight raised panels and framed by full architraves. HISTORIC AMERICAN BUILDINGS SURVEY	

Interior: one large room with paneled dado and overmantel. Stair, ascending at left of fireplace in corner, paneled in about nine risers up, with door; post square with moulded handrail, balusters missing--were square in section, set diagonally very close together on closed stringer.



JOHNSTON - EARLY ARCH. OF N.C., P. 26 (PLAN)

Prepared by

Thomas T. Waterman
1940